

Work Order ID 100668***100668***

Page 1

Friday, April 26, 2013 12:53:21 PM

Item ID: D350-727-043

Accept

N900040100Setup Start ***NS1***

Revision ID:

Stop ***NS2***

Item Name: Wearplate, Longer Aft, LH/RH

Start Date: 4/26/2013 Start Qty: 4.00

4

Cust Item ID:

Required Date: 4/26/2013 Req'd Qty: 4.00

4

Customer:

Reference: disassemble

Approvals:

Process Plan: W

Date: _____

Tooling: _____

Date: _____

Run Start ***NR1***

QC: _____

Date: _____

SPC (Y/N): _____

Date: _____

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

Draw Nbr

Revision Nbr

IIN D350-727

Rev A

110

Pick Kit

0.00

110

Packaging

Memo

0.00

Packaging

PULL FROM STOCK:
2 X D350-727-043 B89667
2 X D350-727-043 B89669DISASSEMBLE KIT
RETURN PARTS TO STK

4X

Sp
13-4-26

140

QC21- Final Inspection - Work Order Release

0.00

140

QC

Memo

0.00

Quality Control

13/5/6

1304.26

Picklist Print

Friday, April 26, 2013 12:53:20 PM

Page 1

Work Order ID: 100668

Parent Item: D350-727-043

Parent Item Name: Wearplate, Longer Aft, LH/RH

Start Date: 4/26/2013

Required Date: 4/26/2013

Start Qty: 4.00

Required Qty: 4.00

Comments: IPP Rev:A05.05.12New issueKJ/JLM VERF:EC IPP REV:B 12.04.11 AS PER ECN 12-546 DD

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3319-1 Wearplate		Manufactured	No				Each	2.0000		4 ⁻⁴ 1385026			SP
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				FG				2					
				85702				2					
D3319-5 Wearplate		Manufactured	No				Each	10.0000		1 ⁻⁴			SP
				<u>Location</u>				<u>Loc Qty</u>		<u>Loc Code</u>			
				ST500				10					
				83508				2		4X			
				89376				8					
D350-727-043 Wearplate, Longer Aft, LH/RH		Manufactured	No				Each	0.0000		4 ⁻			